

## Chiller Low on Freon

- 1) Most likely in ISL chiller
- 2) Symptom: temperature drift over a few hours
- 3) Check for bubbles in Freon sight glass on chiller to confirm low Freon
- 4) Swap ISL and spare chiller ( Instructions)
- 5) Call a Contractor or FESS for leak search & Freon recharge

Coordinate with the Silicon SPLs